



Case Study: Motor Rotor Cracks

Terry Goddard, CAWCD Board President

Steven Romero, Field Maintenance West Manager

Background Information

Amortisseur Winding Function

- Used to accelerate motor during start-up
- Dampen any speed fluctuations or oscillations that may occur due to sudden load changes
- Makes a synchronous motor self-starting like a squirrel-cage induction motor




LHQ U10 Rotor
2250 HP Electric Motor

Damage Identification

July of 2022, 5 Year Motor PM visual inspection performed


- Six broken rotor pole to pole amortisseur winding connections identified by plant electrician
- CAP Maintenance Organization immediately notified of findings



Damage Identification

August 2022, rotor removed from unit for further inspection.


- Confirmed six connections with arcing at some locations
- Three additional connections with hairline cracks
 - Lengths vary from $\sim 3/16"$ to $7/8"$



Damage History

Bouse Hills (BSH) and Little Harquahala (LHQ) small unit motors have a history of cracks with the original design.



- Mid-1990s, 6 of 8 small units were identified having cracks
- Hassayampa (HSY) small unit motors had no history of cracks



Original Pole to Pole
Amortisseur Connection


Repair History

- 1996-2000, all BSH, LHQ, and HSY small units received a design modification.
- Adding reinforcement bar onto lap joint.
 - Brazed in place
- Increased cross section at joint expected to eliminate cracking.



Damage History

- All six broken connections identified on LHQ U10 had the 1990s modifications performed.
- With these results, all small units of BSH, LHQ, and HSY were inspected.
- Cracks were identified on 6 of 12 units



Modified Pole to Pole Amortisseur Connection With Cracks [LHQ U10 – July 21, 2022]

West Small Unit Inspection Results

Unit	Hours	Starts	History			Current	
			Design Modified	Year	Cracked Connections	Inspection	Cracked Connections
BSH U02	58205	1885	Yes	1996	2	Aug. 2022	6
BSH U01	47469	1547	Yes	1996	2	Aug. 2022	0
BSH U09	50530	1246	Yes	1996	4	Sep. 2022	0
BSH U10	47423	1589	Yes	1996	0	Sep. 2022	2
LHQ U01	85619	2437	Yes	1996	2	Sep. 2022	6
LHQ U02	83534	1699	Yes	1996	0	Sep. 2022	1
LHQ U09	76782	1584	Yes	1996	8	Aug. 2022	2
LHQ U10	68463	1852	Yes	1996, 2000	1 - 1996, 3 - 2000	Jul. 2022	6
HSY U01	86441	2123	Yes	1997	0	Sep. 2022	0
HSY U02	66893	1695	Yes	1997	0	Sep. 2022	0
HSY U09	78105	1782	Yes	1997	0	Aug. 2022	0
HSY U10	75915	1912	Yes	1997	0	Aug. 2022	0

8


BSH, LHQ: 16 rotor poles (32 connections)
 HSY: 12 rotor poles (24 connections)

$$N_{\text{poles}} = \frac{\text{Freq}_{\text{Hz}} \times 120}{\text{Speed}_{\text{rpm}}}$$



Suspected Cause

- Insufficient OEM Design
 - Connection not sufficient for operating stresses
 - thermal expansion of rotor during operation (20 °C to 60°C)
 - Inertial forces
- Modifications in 1990s not adequate
 - May have introduced residual stresses (counterproductive)



Functional Impact

Review of unit operating history and test data

- No operational impact to currents, vibrations, and temperatures
- No noticeable change to starting times
- No significant change to motor test results
 - Offline Tests: Doble, PDMA
 - Online Tests: Partial Discharge
- No functional impact observed

Long Term Risks

- Arcing across broken connections
 - Debris thrown out into the stator end turns, possibly resulting in insulation failure.
- Additional broken connections result in single rotor poles no longer part of amortisseur winding electrical circuit
 - Impact to motor starting times and synchronization




Risk Mitigation Efforts – Near Term

- Prioritize operation of units without cracks.
- If a unit with cracks must be operated, recommend that this unit become a constant runner.
 - Pole to pole connection experience significant current flow and the most force during the start sequence of motor before synchronization.
 - Pole to pole connections experience the most thermal growth/contraction during the starting and stopping of the motors.
 - Reducing the frequency of starting and stopping of damaged units will help mitigate risk of any additional damage.

Risk Mitigation – Long Term

- Design modification performed by supplier specializing in motor repairs



Modify Design with Flexible Pole to Pole
Amortisseur Winding Connectors

Estimated Repair Scope & Costs

Estimated Repair scope

- Remove rotor (CAP)
- Visual inspect and evaluate connection modifications (Contractor)
- Electrically test rotor – pole drop, insulation resistance (Contractor)
- Steam clean and bake rotor (Contractor)
- Perform insulation resistance test (Contractor)
- Perform connection modification (Contractor)
- Final electrical testing - pole drop, megger (Contractor)
- Reassemble rotor (CAP)

Estimated repair costs

- CAP Labor: ~700 hrs.
- Contractor Repair Services : \$56,361
 - Material: \$6,136.16
 - Contractor Labor: \$50,224.84
 - Repair Time: 6-8 weeks

Repair Plan

